

420 SEL 1991 Before Treatment



Valve



Piston 1



Piston 2



Piston 3+Cyl Wall

“Inspection confirmed crucial performance degrading carbon build up. Pictures show this carbon build up especially in the areas of the intake valve and the piston crown. Some carbon and discoloration or dulling was also noticed on the cylinder walls.”

Pictures are courtesy of European Performance, Dallas, Texas, using a Visual Inspection Device BK 6000. These pictures are of the vehicle inspected, which is listed at the top of the page, and issued to ceramic Performance Worldwide, LLC for their exclusive use and publication.