420 SEL 1991
After CerBond® Treatment

Valve

Piston 1

Piston 2

Piston 3+Cyl Wall

"Re-inspection, following a CerBond® treatment and driving the vehicle for 1,500+ miles, confirmed performance degrading carbon build up has been basically eliminated. These after pictures show the metal minus the carbon build up. The intake valve and the piston crown both are carbon free and marks where the carbon had built up in thick layers is now visible in a few areas. Cylinder walls are now shiny and actually have a transparent amber coating seal."

Pictures are courtesy of European Performance, Dallas, Texas, using a Visual Inspection Device BK 6000. These pictures are of the vehicle inspected, which is listed at the top of the page, and issued to ceramic Performance Worldwide, LLC for their exclusive use and publication.

© 2009, 2010 ceramic Performance Worldwide, LLC